

Audit Report

TILP

OFFICE OF INSPECTOR GENERAL

UNITED STATES POSTAL SERVICE

500

B2

Deposit by Mail Controls at Selected Mail Processing Facilities

1 4

Report Number NO-AR-19-007 | September 12, 2019

Table of Contents

Cover	
Highlights	1
Objective	1
What the OIG Found	2
What the OIG Recommended	
Transmittal Letter	
Results	4
Introduction/Objective	4
Background	4
Finding #1: Security Deficiencies Not Addressed	
Management Corrective Action	6
Recommendation #1	6
Recommendation #2	
Management's Comments	
Evaluation of Management's Comments	
Appendices	8
Appendix A: Additional Information	9
Scope and Methodology	
Prior Audit Coverage	
Appendix B: Audit Checklist	
Appendix C: Management's Comments	12
Contact Information	

Highlights

Objective

Our objective was to assess controls and actions taken by the U.S. Postal Service to address identified security deficiencies surrounding the Postal Service's Deposit by Mail (DBM) service at **Control** mail processing facilities.

At the request of a business customer, the Postal Service initiated a new service in February 2015 called DBM, which allows cash and high-value mailings to be sent through the Postal Service Priority Mail system. The customer has 16,000 retail customer locations throughout the country that participate in the DBM service. The high-value DBM mail is handled and processed like any other Priority Mail.

The customer's retail location sends their via Priority Mail to the customer's headquarters in turn, the customer's headquarters sends throughout the country. Incoming and outgoing Priority Mail envelopes originate and destinate through three mail processing facilities:

Postal Inspection Service and

Postal Service personnel are responsible for security at these locations while the Postal Service has custody of the mail.

The customer's annual DBM mail volume increased from about

service generated about

million in revenue for the Postal Service during this

mailpieces from June 2018 to May 2019. The DBM

time period. We estimate that the business customer mailed about

through the DBM service from June 2018 to May 2019. The

DBM service currently

Postal Service Handbook RE-5, *Building and Site Security Requirements,* covers the security of personnel, buildings, and mail on site and security of mail and Postal Service assets within a building. Since 2018, the Postal Inspection

Service's has conducted six security reviews at the three mail processing facilities. Specifically, Vulnerability Risk Assessment Tool (VRAT) reviews of facility security were performed at the

VRAT is the tool the Postal Inspection Service and Postal Service employees use to identify security risks and vulnerabilities at facilities.

The Postal Inspection Service conducted two additional security reviews of the DBM service at the

Security reviews are

addendums to VRATs. The two security reviews examined the protocols and security practices at Postal Service facilities that process, transport, and deliver the customer's **security reviews**. From the various security reviews, we identified 14 high-risk security deficiencies which impact the DBM service and determined the actions management has taken to respond to the Postal Inspection Service security reports and address these deficiencies.

The Postal Service did not properly address the 14 high-risk security deficiencies identified by the Inspection Service for the **Service Service** mail processing facilities which process DBM mail. We also identified three additional high-risk security deficiencies during our site observations at the three facilities in June 2019.

The deficiencies included:

- Lack of cameras at DBM mail processing and handling facilities (three deficiencies at the three facilities). Cameras that provide full coverage of the mail processing machines that process the DBM mail are needed.
- Unsecured doors (five deficiencies at the three facilities), including exterior doors with badge readers and interior doors left open, propped, or broken.
- Unsecured staged DBM mail (four deficiencies at two facilities). DBM mail is staged outside of secured areas and is accessible to unauthorized personnel.
- Inadequate rewrap procedures for DBM mail (four deficiencies at one facility). The rewrap area is where damaged or broken parcels are repaired. It is accessible by unauthorized personnel and is not fully covered by camera views. In addition, DBM mail is comingled with other mail.
- Personal items were left on the workfloor (one deficiency at one facility).

"When management does not properly address security deficiencies there is an increased risk of mail theft." These conditions occurred because plant officials did not properly coordinate with the Postal Inspection Service to properly address security deficiencies. In addition, Standard Operating Procedures (SOPs) were not developed for high-value Priority Mail such as the DBM service.

When security deficiencies are not properly addressed, there is an increased risk of mail theft. According to DBM business customer records, nearly

facilities for the period February through July 2019. Lost and stolen mail reflects poorly on the Postal Service's brand and public image and leaves the agency open to customer complaints.

What the OIG Recommended

We recommended management:

- Establish SOPs for the DBM service to include security cameras, secured doors, staged mail, and adequate rewrap procedures.
- Instruct plant management to properly address security deficiencies identified by the Postal Inspection Service, in a timely manner.

Transmittal Letter

OFFICE OF INSPECTOR GEN UNITED STATES POSTAL SE	
September 12, 2019	
MEMORANDUM FOR:	ROBERT CINTRON VICE PRESIDENT, NETWORK OPERATIONS DISTRICT MANAGER, DISTRICT E-Signed by Inspector General
FROM:	Darrell E. Benjamin, Jr. Deputy Assistant Inspector General for Mission Operations
SUBJECT:	Audit Report – Deposit by Mail Controls at Selected Mail Processing Facilities (Report Number NO-AR-19-007)
	esults of our audit of the Deposit by Mail Controls at Selected (Project Number 19XG011NO000).
	ation and courtesies provided by your staff. If you have any nal information, please contact Margaret McDavid, Director, e at 703-248-2100.
Attachment	
cc: Postmaster General Corporate Audit Response Management Vice President, Universident, Supply Management Chief Postal Inspector, Postal Inspection Service	

Results

Introduction/Objective

This report presents the results of our self-initiated audit of the Deposit by Mail Controls at Mail Processing Facilities (Project Number 19XG011NO000). The objective of our audit was to assess controls and actions taken by the U.S. Postal Service to address identified security deficiencies surrounding the Postal Service's Deposit by Mail (DBM) service at mail processing facilities.

Background

The Postal Service, at the request of a business customer, initiated a new service in February 2015 called DBM, which allows cash and high-value mailings to be sent through the Postal Service Priority Mail¹ system. The customer has

customer locations that participate in the DBM service. High-value DBM mail is handled and processed like any other Priority Mail.

The business customer routes its incomin through	g and outgoing
"The Postal Service did not properly address security deficiencies surrounding the DBM service at the three mail processing facilities."	The Postal Inspection Service and Postal Service personnel are responsible for security at these The customer's annual DBM mail volume increased from about mailpieces from June 2018 to May 2019. The DBM service



identify facility security risks and vulnerabilities.

The Postal Inspection Service has conducted two additional security reviews of the DBM service, at the

Security reviews

are addendums to VRATs. The two security reviews examined the protocols and security practices at the Postal Service facilities that process, transport, and deliver the customer's deposit and change orders. From these reviews we identified 14 high-risk security deficiencies which impact the DBM service and determined

Finding #1: Security Deficiencies Not Addressed

The Postal Service did not properly address security deficiencies surrounding the DBM service at the three **Security** mail processing facilities. Specifically, the 14 high-risk security deficiencies the Inspection Service identified for the three **Security** mail processing facilities which process DBM mail were not properly addressed. In addition, we identified three additional high-risk security deficiencies during our site observations (see Appendix B for details).

Priority Mail is an expedited service of mailable matter weighing no more than 70 pounds with a service objective for delivery of one to three days.

Deficiencies included:

- Lack of cameras at DBM mail processing and handling facilities (three deficiencies at the three facilities). Cameras that provide full coverage of the mail processing machines that process the DBM mail are needed.
- Unsecured doors (five deficiencies at the three facilities), including exterior doors with badge readers and interior doors left open, propped or broken (see Figure 1).
- Unsecured staged DBM mail (four deficiencies at the
 DBM mail is staged outside of secured areas and is accessible to unauthorized personnel (see Figure 2).
- Inadequate rewrap procedures for DBM mail (four deficiencies at the indequate rewrap procedures for DBM mail (four deficiencies at the indequate rewrap procedures). The rewrap area is where damaged or broken parcels are repaired⁴ and is accessible by unauthorized personnel and not fully covered by camera views. In addition, DBM mail is comingled with other mail and unnecessary items should be removed from the rewrap area (see Figure 3).
- Personal items were left on the workroom floor (one deficiency at the
).

These conditions occurred because plant officials did not properly coordinate with the Postal Inspection Service to properly address the identified security deficiencies. In addition, Standard Operating Procedures (SOPs) were not developed for high-value Priority Mail such as the DBM service.

When management does not properly address security deficiencies there is an increased risk of mail theft. According to DBM business customer records, nearly

from mail

processing facilities for the period February through July 2019. Lost or stolen mail reflects poorly on the Postal Service's brand and public image and leaves the agency open to customer complaints.

Figure 1. Propped Door

"When management does not properly address security deficiencies there is an increased risk of mail theft."



Unsecured exterior door propped open. Source: OIG photograph taken at the

⁴ Handbook M-32, *Management Operating Data System (MODS)*, dated September 2018.

Figure 2. Unsecured Staged DBM Mail



DBM mail from the previous evening is outside the cage. equipment on the left side of the aisle. Source: OIG photograph taken at the including DBM mail, is in the Postal

Management Corrective Action

During our audit, the

plant manager issued a memorandum

dated June 27, 2019, to all plant employees prohibiting personal belongings on the workroom floor; therefore, we are not making a recommendation regarding this issue.

Figure 3. Cluttered Rewrap Area



The box, flat tubs, and hard hat are examples of items that need to be removed from the rewrap area. Source: OIG photograph taken at the

Recommendation #1

The **Vice President**, **Network Operations**, establish standard operating procedures for the Deposit by Mail service to include security cameras, secured doors, staged mail, and adequate rewrap procedures.

Recommendation #2

The **District Manager**, **District**, in coordination with the Vice President, Network Operations, instruct plant management to properly address security deficiencies identified by the Postal Inspection Service, in a timely manner.

Management's Comments

Management agreed with the findings and recommendation 2 and partially agreed with recommendation 1.

Regarding recommendation 1, management stated that there is no official DBM program and that the **Section** District is the only location where a DBM process has been established. Also, the **Section** District plants have implemented a SOP for the handling of deposits by mail and rewrap procedures and provided details with their response letter. Management stated in the event of a development and establishment of a national service for DBM, a national SOP will be developed. Additionally, the Postal Inspection Service has installed security cameras at the **Security** and will be installing cameras at the **Security** and will be installing cameras at the **Security** and will be installing cameras at the **Security**.

The target implementation date is November 30, 2019.

Regarding recommendation 2, management stated that they have reissued service talks to employees at the mail processing facilities addressing employee responsibility concerning building security and protection of the mail. In addition, they stated that all security deficiencies identified by the Postal Inspection Service related to facility entry and exit points, and security cameras will be corrected. The target implementation date is November 30, 2019.

See Appendix C for management's comments in their entirety.

Evaluation of Management's Comments

The OIG considers management's comments responsive to the recommendations in the report and corrective actions should resolve the issues identified in the report. Regarding management's statement concerning the existence of an official DBM program, we revised the final report to reflect that this is not an official program and instead refer to it as a service. Concerning the SOP, during the course of our audit, management developed a SOP for the District plants. We agree that in the event DBM is expanded nationally, a national SOP should be developed.

All recommendations require OIG concurrence before closure. Consequently, the OIG requests written confirmation when corrective actions are completed. Recommendations should not be closed in the Postal Service's follow-up tracking system until the OIG provides written confirmation that the recommendations can be closed.

Appendices

Click on the appendix title below to navigate to the section content.

Appendix A: Additional Information	9
Scope and Methodology	9
Prior Audit Coverage	9
Appendix B: Audit Checklist	10
Appendix C: Management's Comments	12

Appendix A: Additional Information

Scope and Methodology

The scope of this project was security deficiencies surrounding the Postal Service's DBM service at the mail processing facilities. These facilities include the To accomplish our objective, we reviewed six Postal Inspection Service security reviews and conducted observations of the DBM service at the mail processing facilities and identified 17 high-risk security deficiencies which impact the DBM service. These reviews included: Four Postal Inspection Service VRAT reports at the mail processing

- facilities,
- Two Postal Inspection Service supplemental security reviews at mail processing facilities, dated

We also observed DBM mailings at the three **mail** mail processing facilities. In addition, we interviewed Postal Service managers at the three

area mail processing facilities and District to

determine the actions management has taken to address the 17 high-risk security deficiencies.

We conducted this performance audit from June through September 2019, in accordance with generally accepted government auditing standards and included such tests of internal controls as we considered necessary under the circumstances. Those standards require that we plan and perform the audit to obtain sufficient, appropriate evidence to provide a reasonable basis for our findings and conclusions based on our audit objective. We believe that the evidence obtained provides a reasonable basis for our findings and conclusions based on our audit objective. We discussed our observations and conclusions with management on August 9, 2019, and included their comments where appropriate.

We assessed the reliability of DBM package volume data and revenue by interviewing agency officials knowledgeable about the data. We determined that the data were sufficiently reliable for the purposes of this report.

Prior Audit Coverage

The OIG did not identify any prior audits or reviews related to the objective of this audit conducted within the last five years.

Appendix B: Audit Checklist

ltem	Location	High-Risk Security Deficiency	OIG Observations
1		The camera system is not adequately located in the facility to monitor deposit by mail (DBM) mailings throughout the facility. <i>Source:</i> U.S. Postal Inspection Service (USPIS) VRAT review, April 6, 2018.	There was one camera outside the second second . Its view of the cage door and inside the cage was obstructed. There was a fixed camera on the dock, which was not used as the assigned door for second second sec
2		Badge entry point doors are not all secured and fully operational. <u>Source:</u> USPIS VRAT review, April 6, 2018.	We observed badge entry doors purposely disabled. Another badge entry door was broken and could not be closed.
3		The holding area for DBM mail awaiting sectors is not secure. <u>Source:</u> OIG observations, June 19, 2019.	We observed an unlocked interior door leading to the DBM mail holding area. There was also open unsecured access at both ends of the window unit leading to the holding area.
4		The DBM mail is not properly secured on the P&DC workroom floor. Source: OIG observations, June 19, 2019.	DBM mail was staged in an unattended location outside the cage prior to being worked.
5		The DBM mail is not worked and secured in the cage. <u>Source:</u> USPIS security review, March 5, 2019.	DBM mail was processed outside of the second second I cage, which was cluttered with empty mail containers. Also, we noted unsupervised couriers around the staged DBM mail.
6		Exterior doors are not fully functional with regards to an audible alarm signaling that the doors were open. <u>Source:</u> USPIS VRAT review, April 4, 2019.	Exit doors were propped open and the audible alarm was not operational.
7		Cameras do not cover DBM mail on the machines that process this mail. <u>Source:</u> USPIS security review, March 5, 2019.	Additional cameras are needed to fully view the mail processing machines that process DBM mail.
8		Sufficient cameras are not in place to monitor and observe the movement and separation of DBM mail throughout the facility. The ability to view and record transactions of DBM mail is limited because dedicated cameras are not in place to obtain a clear view of the arrival and unloading process. <u>Source:</u> USPIS security review, March 5, 2019.	Some of the lookout galleries and cameras are blocked by conveyor belts and other equipment. This creates blind spots in the building where DBM mail cannot be observed throughout the facility.
9		The DBM mail is not staged in a secure area after the mail has been processed. <u>Source:</u> OIG observations, June 18-19, 2019.	DBM mail was staged with the other unsecured processed Priority Mail.

ltem	Location	High-Risk Security Deficiency	OIG Observations
10		Employees placed personal bags or items on the workroom floor.	Several employees were observed bringing personal bags on
		<u>Source:</u> USPIS Security Review, March 5, 2019.	the workroom floor.
11	-	Twenty of the 21 exterior doors in the facility were unable to lock mechanically. The doors are equipped with emergency exit panic bars (EPBs). The EPBs disengage when the doors are open from the outside, allowing entrance into the building.	Twenty of the 21 exit doors were not locked and none of the EPBs were operational.
		Source: USPIS VRAT Review, April 25, 2018.	
12	_	Not all doors have the access control system. The access control system is present only at the main entrance to the plant.	Only 1 of the 21 exit doors had an access control system. The
		Source: USPIS VRAT Review, April 25, 2018.	only door that had one was the main entrance door.
13		The entrance to the rewrap area is not restricted to only two assigned personnel.	The audit team observed five employees working in the rewrap
		Source: USPIS Security Review, September 27, 2018.	area during site visit.
14		Items were in the damaged mail section that did not belong in the area. These items obstruct the cameras from observing the employees working in the damaged mail area.	Clutter in the damaged mail section needed to either be organized or removed to eliminate obstructions that prevent cameras from observing the employees working in the area.
		Source: USPIS Security Review, September 27, 2018.	cameras from observing the employees working in the area.
15		The damaged mail area does not have a secure place to stage DBM mailings.	DBM damaged mail was located in an unlocked fenced-in area.
		Source: USPIS Security Review, September 27, 2018.	Den damaged mail was located in an unlocked feliced-in afed.
16		The DBM mail is not moved around the workroom floor in a secure container.	DBM mail was moved on regular, unsecured Postal Service
		Source: USPIS Security Review, September 27, 2018.	equipment through the facility.
17		The incoming and outgoing recording method detailing the final resolution of rewrapped mail has not been updated.	Management was unable to provide a recording log for
		Source: USPIS Security Review, September 27, 2018.	the rewrap area.

Appendix C: Management's Comments







Contact us via our Hotline and FOIA forms. Follow us on social networks. Stay informed.

> 1735 North Lynn Street Arlington, VA 22209-2020 (703) 248-2100

For media inquiries, contact Agapi Doulaveris Telephone: 703-248-2286 adoulaveris@uspsoig.gov